

Car buying made simple.





Stock#: T58725A Year: 2017 Make: TOYOTA Model: CAMRY Trim: LE

Powertrain: FWD Miles: 6K Gas Mileage: 24/33 VIN #: 4T1BF1FK5HU624592

Why should I choose Bobby Rahal Toyota?

Conducting fair and honest business transactions with our clients has always been the Bobby Rahal Automotive Group "brand". We are taking this approach to a new level by drawing a clear distinction between our group and other dealers who rely on games, gimmicks, and confusing advertisements designed to attract your attention. We encourage you to see us before you buy. Our goal is to ensure you have the most enjoyable car buying and ownership experience - bar none.

What is Live Market Driven Pricing?

We give you posted prices upfront (Which is the same price whether you choose to shop on the internet, by telephone, or at the dealership) researched to beat the back and forth negotiated prices offered elsewhere in the market. We don't start with inflated prices hoping to win a "negotiating" contest with you, our valued client. We provide an "upfront price" not only on the vehicle, but also on all prices down the line - finance rates, extended warranties, accessories, paint and fabric protection, and trade in values that we guarantee whether you buy from us or from someone else.

How do you come up with your Live Market Driven Pricing?

First, we use software that scours the market to collect the appropriate information, far beyond just year, make, model and trim level. Second, we identify and compare every identical vehicle according to every factor that matters including supply and demand. Finally we use this data to accurately price our cars to the market and offer you the best value.

WHY TOYOTA CERTIFIED?

We check 160 points. All to prove one point: Only the best get to be Toyota Certified Used Vehicles. Our certification process keeps you in mind every step of the way. The TCUV standards apply from the time a Toyota dealer acquires the vehicle through to the final sale. Prior to the rigorous 160-point inspection every certified Toyota goes through, a CARFAX vehicle history report is reviewed to ensure that only the best of the best vehicles receive the Toyota Certified Seal of approval. Now how's that for peace of mind?

The Toyota Certified Used Vehicle Advantage Includes:

- 12-month/12,000-mile Limited Comprehensive Warranty
- 7-year/100,000-mile Limited Powertrain Warranty
- 1-year of Roadside Assistance
- 160-Point Quality Assurance Inspection
- CARFAX® Vehicle History Report
- Certified Warranty honored at over 1,400 Toyota dealers in the U.S. and Canada

160-Point Quality Assurance Inspection Check Sheet







DO NOT TEAR APART AT PERFORATION

This Inspection Check Sheet must be 1) completed with <u>all</u> items checked, 2) signed by responsible persons as indicated, and 3) retained along with repair orders and Vehicle History Report in the vehicle's service history file.

Year/Make/Model: Ext. Color: Int. Color: VIN:	Dealership Name: BOBBY RAHAL TOYOTA										De	ale	er (Cod	de	:_				37	<u>71</u>	49					
Mechanical Certification See Mechanical Standards and Process Notes For Additional Dotalisty Wilk a Dealer Code Check Mechanical Standards and Process Notes For Additional Dotalisty Wilk a Dealer Code Check Mechanical Standards and Process Notes For Additional Dotalisty Wilk a Dealer Code Check Mechanical Standards and Process Notes For Additional Dotalisty Wilk a Dealer Code Check Mechanical Standards and Process Notes For Additional Dotalisty Wilk a Dealer Code Check Mechanical Standards and Process Notes For Additional Dotalisty Wilk a Dealer Code Check Mechanical Standards and Process Notes For Additional Dotalisty Wilk and Process Office Wilk and Pr	Yea	ar/Make/Model:				Stock Number:																					
Mechanical Standards and Process Notes For Additional Details	Ext	t. Color: Int. Color:		\	/IN:																						
See Mechanical Standards and Process Notes For Additional Details	Da	te Acquired: Date Inspected: _				R.O	. Nu	mbe	:-							[Mil	ea	ge	:							
VIN & Dealer Code Check Sum and print Vehicle History Report and attaich Ran and print Vehicle History Report And Print Report And Print Report Print		Mechanical Certification						_			_				_		_						-	Meets	Adjus	st/	
VIN & Dealer Code Check 1 Run and print Verticel History Report and attach Run and print Verticel History Report and attach Run and print Verticel History Report and attach Run a logistic History Report Act and the logistic History Report In dealer Interest Property Cold engine operation performs property Throttle operates property during operating temperature Proprint Property Run and Property Run and Property Run and	(S	ee Mechanical Standards and Process Notes For Addi	itiona	al Det	ails)		10										-		-	no le:	aks			Stds	Repa	iir I	N/A
Run and print Vehicle History Report and attach Run a Tachstman Health Check and retain the diagnostic sport in dolar file check for and perform outstanding Recalls and applicable SSCs All floor tream and the print of 5/22* tread depth remaining across tread with All floor tream and the print of 5/22* tread depth remaining across tread with All floor tream and the print of 5/22* tread depth remaining across tread with All floor tream and the print of 5/22* tread depth remaining across tread with All floor tream and the print of 5/22* tread depth remaining across tread with All floor tream and floor and		VIN 9 Declay Code Cheek	Meets	Adjust																							
Runa Techstream Health Check and retain the diagnostic report in delater file cheer for the contract of the co	4		Stds	Repai	r N/A															_		dama	ge				
Road Test Road Test Cold engine operation performs properly during cold stand applicable SSCs Road Test Cold engine operation performs properly Throttle operates properly during ocal stand to the standard ocal stands and standard to the standard ocal standard to the standard to	'	, , , , , , , , , , , , , , , , , , , ,					43	Minir	nun	of 5/	/32"	trea	ad c	lepth	n re	mai	ining	g ac	ros	s trea	ad v	width .	•				
Road Test							44							ame	bra	and,	, mo	odel	, siz	e, tre	ead	design	٦,				
Road Test		Check for and perform outstanding Recalls and applicable SSCs					1,5					_															
Cold engine operation performs properly																				_		,	је				
3 Throttle operates properly during oold start							40						ııaıı	is ai	HE	eue	eu e	qui	JITIE	#IIL (S	11111	ı Kıt,					
4 Vehicle operates properly during warm-up conditions 5 Engine performs properly during operating temperature 6 Engine performs properly during operating temperature 7 Engine fan(s) operate properly 8 Brake pedal free play and travel within specifications 9 No abnormal vibrations and noises during brake applications 10 ABS operates properly with no signs of wear 11 Parking brake operates properly with from signs of wear 12 Seats belt and the play and within specification 13 Seat belts operate properly with no signs of wear 14 Transmission/clutch operates properly with full extension and smooth operation 14 Transmission operates properly during cold temperature 16 Automatic transmission operates properly during cold temperature 16 Automatic transmission operates properly during cold temperature 17 Steering wheel centered in straight-line driving 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight not level surface 20 Tilt and telescopic steering mechanism operates properly in all modes 21 Front windshield wiper operates properly in all modes 22 Windshield washer fluid sprays properly 23 Windshield washer fluid sprays properly 24 Wiper blades clear glass properly 25 Speadometer functions properly 26 Speadometer functions properly 27 Odometer application registers mileage in every mode 28 Couries control operates properly 39 No abnormal sign or vibration from engine 31 No abnormal and or vibration from engine 32 No excessive wind or road noise 33 No abnormal noise or vibration from engine 34 No excessive wind or road noise 35 Suspension-related items for wear/leaks and proper performance 48 Brake rotes from properly yin the order to depend and provided to the vehicle 49 Exhaust system is properly yin the order and selection of the vehicle 50 Firms operates properly and within specification 51 Provided to the vehicle of the veh							47	Brak	е ра	d/sho	e lin	ings	hav	ean	nini	mur	n th	ickn	ess	of 50)%	emaini	ng				
5 Engine performs properly during operating temperature 6 Engine reaches normal operating temperature 7 Engine far(s) operate properly 8 Brake pedal free play and travel within specifications 9 No abnormal vortations and noises during brake applications 10 ABS operates properly (via Techstream Health Check) 11 Parking brake operates properly and motivations and noises during brake applications 12 Seat belt material condition 13 Seat belts operate properly with full extension and smooth operation 14 Transmission control operates smoothly 15 Automatic transmission operates properly during cold temperature 16 Automatic transmission operates properly during operating temperature 17 Steering has normal feel in lock-to-lock turning 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight on level surface 20 Titl and telescopic steering mechanism operates properly 21 Front windshield wiper operates properly in all modes 22 Rear windshield wiper operates properly in all modes 23 Mindshield washer fluid sorsy properly 24 Wiper blades clear glass properly 25 Wipers return to correct position when off 26 Speedometer functions properly 27 Odometer application registers mileage in every mode 28 Rounds and the property 29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal sequeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 5 Trans-Librody condition 5 Explain and the interior of the vehicle Frame, Structure & Underbody 5 Trans-Librody condition 5 Superation-related items for wear/leaks and proper performance 5 Indication registers mileage in every mode 6 Colorant specific gravity to -31* Fahrenheit 6 Perform batting transplantial residence of properly 6 Colorant specific gravity to -31* Fahrenheit 7 Change engine oil and filter 7 Change engine oil and filter 8 District of the vehicle of the vehicle Frame, Structure & Underbody 7 Change engine oil and filter 8 District	l .		H	_			48	Brak	e ro	tors/c	Irun	ารุพ	ithir	n spe	ecif	icat	ions	s wi	th n	o abı	nor	mal					
6 Engine reaches normal operating temperature 7 Engine fanisk) operate properly 8 Brake pedal free play and travel within specifications 9 No abnormal vibrations and noises during brake applications 10 ABS operates properly with fall entails Check) 11 Parking brake operates properly and within specification 12 Seat better material condition 13 Seat betts operate properly with full extension and smooth operation 14 Transmission/clutch operates properly during cold temperature 15 Automatic transmission operates properly during operating temperature 16 Automatic transmission operates properly during operating temperature 17 Steering has normal feel in lock-to-lock turning 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight on level surface 19 Tit and telescopic steering mechanism operates properly 19 Vehicle tracks and drives straight on level surface 19 Air filter in good condition 19 Will and telescopic steering mechanism operates properly 19 Will and telescopic steering mechanism operates properly 20 Will and telescopic steering mechanism operates properly 21 Will and telescopic steering mechanism operates properly 22 Will and telescopic steering mechanism operates properly 23 Will and telescopic steering mechanism operates properly 24 Will profit had to decals 25 Speedometer functions properly 26 Will profit had the straight on level straight on level decals and decals 27 Straight on level surface 28 Speedometer functions properly 29 Heater operates properly 30 Air Coperates properly 31 No abnormal sequence of unders of the vehicle 32 No excessive wind or road noise 33 No abnormal sequence with the interior of the vehicle 34 No abnormal sequence with the interior of the vehicle 35 Frame / Unitody condition 36 Suspension-related items for wear/leaks and proper performance 36 Suspension-related items for wear/leaks and proper performance 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 39 Suspension-related items for wea			H	Н				-	_																		
Principle fan(s) operate properly S Prake pedal free play and travel within specifications S Prake pedal free play and travel within specifications S Prake pedal free play and travel within specifications S Prake pedal free play and travel within specifications S Prake pedal free play and travel within specifications S Prake pedal free play and travel within specifications S Prake pedal free play and travel within specifications S Prake pedal free play and travel within specification S Prake pedals properly with no damage S Prake pedals properly with no dalays S Prake pedals properly sized and secure S Prake pedals properly			П	П																	100	of	۰.	Н	Н		
19 No abnormal vibrations and noises during brake applications 10 ABS operates properly (with Techstream Health Check) 11 Parking brake operates properly (with Techstream Health Check) 12 Seat belts operates properly and within specification 13 Seat belts operates properly with full extension and smooth operation 14 Transmission/clutch operates properly during cold temperature 15 Automatic transmission operates properly during operation 15 Automatic transmission operates properly during operation 16 Automatic transmission operates properly during operation 17 Steering has normal feel in lock-to-lock turning 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight to nevel surface 19 Vehicle tracks and drives straight tracks a	7	, , ,	Ī	П				_													igns	or wea	11	H			
19 No abnormal vibrations and noises during brake applications 10 ABS operates properly (with Techstream Health Check) 11 Parking brake operates properly (with Techstream Health Check) 12 Seat belts operates properly and within specification 13 Seat belts operates properly with full extension and smooth operation 14 Transmission/clutch operates properly during cold temperature 15 Automatic transmission operates properly during operation 15 Automatic transmission operates properly during operation 16 Automatic transmission operates properly during operation 17 Steering has normal feel in lock-to-lock turning 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight to nevel surface 19 Vehicle tracks and drives straight tracks a	8	Brake pedal free play and travel within specifications																		_	oor			H	H		
10 ABS operates properly (wita Techstream Health Check) 11 Parking brake operates properly and within specification 12 Seat belts operate properly with full extension and smooth operation 13 Seat belts operate properly with full extension and smooth operation 14 Transmission/clutch operates properly during cold temperature 15 Automatic transmission operates properly during operating temperature 16 Automatic transmission operates properly during operating temperature 17 Steering has normal feel in lock-to-lock turning 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight on level surface 20 Tilt and telescopic steering mechanism operates properly 21 Front windshield wiper operates properly in all modes 22 Windshield wiper operates properly in all modes 23 Windshield wiper operates properly 24 Wiper blades clear glass properly 25 Wipers return to correct position when off 26 Speedometer functions properly 26 Cruise control operates properly 27 Odometer application registers mileage in every mode 28 Cruise control operates properly 29 Heater operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal rive vibration/steering wheel shimmy during road test 4 No abnormal speake/artities within the interior of the vehicle Frame, Structure & Underbody 5 Indication 6 Perform emissions as and pan for leaks 5 Differential fluid level correct with no leaks Emissions & State Inspection 6 Performe emissions test and/or state inspection, if required 15 Differential fluid level correct with no leaks 16 Differential fluid level correct with no leaks 16 Differential fluid level correct with no leaks 16 Parisom emissions test and/or state inspection, if required 16 Parisom emissions test and/or state inspection, if required 17 Differential fluid level correct with no leaks 18 Emissions & State Inspection 16 Perform emissions test and/or state inspection, if required 18 Battery beats and heads 18 Confirm under-hood labels and decals	9	No abnormal vibrations and noises during brake applications																,	_					H	H		ш
11 Parking brake operates properly and within specification 12 Seat belts operate properly with full extension and smooth operation 13 Seat belts operate properly with full extension and smooth operation 14 Transmission/clutch operates smoothly 15 Automatic transmission operates properly during cold temperature 16 Automatic transmission operates properly during operating temperature 17 Steering has normal feel in lock-to-lock turning 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight on level surface 20 Tilt and telescopic steering mechanism operates properly managed	10	ABS operates properly (via Techstream Health Check)								_														Ħ	П		
Seat belts operate properly with full extension and smooth operation																								П	П		
14 Transmission/clutch operates smoothly 15 Automatic transmission operates properly during cold temperature 16 Automatic transmission operates properly during operating temperature 17 Steering has normal feel in lock-to-lock turning 18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight on level surface 20 Tilt and telescopic steering mechanism operates properly 21 Front windshield wiper operates properly in all modes 22 Rear windshield wiper operates properly in all modes 23 Windshield washer fluid sprays properly 24 Wiper blades clear glass properly 25 Wipers return to correct position when orf 26 Speedometer functions properly 27 Odometer application registers mileage in every mode 28 Cruise control operates properly 29 Heater operates properly 30 A/C operates properly 31 No abnormal frie vibration/steering wheel shirmry during road test 33 No abnormal fire vibration/steering wheel shirmry during road test 44 No abnormal size or vibration from engine 35 No excessive wind or road noise 46 Charles and fite 47 Cover body and underbody 48 Frame/Unlibody condition 49 Frame, Structure & Underbody 40 Frame/Unlibody condition 40 Cover body and underbody condition 41 Road proper performance 42 Francy (and proper performance) 43 Suspension-related items for wear/leaks and proper performance 44 No abnormal fire some and proper performance 45 Perform emissions test and/or state inspection, if required 46 Confirm under-hood labes and decals 55 Air filter in good condition 55 Air filter in good condition 60 Battery hosts and cables free of cracks and damage 61 Perform battery check with Midtronics GR8 61 Perform decays and decals 61 Perform battery check with Midtronics GR8 61 Perform battery check with Midtronics decays 61 Perform battery check with Midtronics GR8 62 Battery properly sized and secure 63 Battery properly sized and secure 64 Charging system operating properly and within specification 65 Engine coolant level within specification 66 Coolant specific gravity to -31° Fahrenh			Ц																								_
15 Automatic transmission operates properly during cold temperature																								_	_		_
16 Automatic transmission operates properly during operating temperature		·	H				56	Perf	orm	emiss	sion	s te	st a	nd/o	r st	ate	ins	oec.	tion	, if re	qui	red					
17 Steering has normal feel in lock-to-lock turning			=	H	H			Unc	ler	Hoo	d																
18 Steering wheel centered in straight-line driving 19 Vehicle tracks and drives straight on level surface 20 Tilt and telescopic steering mechanism operates properly 21 Front windshield wiper operates properly in all modes 22 Rear windshield wiper operates properly in all modes 23 Windshield washer fluid sprays properly 24 Wiper blades clear glass properly 25 Wipers return to correct position when off 26 Speedometer functions properly 27 Odometer application registers mileage in every mode 28 Cruise control operates properly 30 A/C operates properly 31 No abnormal fire vibration/steering wheel shimmy during road test 33 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 58 Confirm under-hood labels and decals 59 Air filter in good condition 60 Battery has no visible damage 61 Perform battery check with Midtronics GR8 62 Battery posts and cables free of corrosion and damage 63 Battery properly sized and secure 64 Charging system operating properly and within specification 65 Engine coolant level within specification 66 Coolant specific gravity to -31° Fahrenheit 67 Change engine oil and filter 68 Check for evidence of oil gel 69 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated Frunctional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned			H	H			57					ses	fre	e of	cra	cks	and	d da	ıma	qe				П	П		
19 Vehicle tracks and drives straight on level surface		9	H	П																J -				П	П		
20 Tilt and telescopic steering mechanism operates properly 1 1 1 1 1 1 1 1 1		y y	П				59	Air fi	lter i	n god	d c	ond	itior	1													
22 Rear windshield wiper operates properly in all modes 23 Windshield washer fluid sprays properly 24 Wiper blades clear glass properly 25 Wipers return to correct position when off 26 Speedometer functions properly 27 Odometer application registers mileage in every mode 28 Cruise control operates properly 29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance Gabattery posts and cables free of corrosion and damage Gabattery posts and cables free of corrosion and damage Gabattery posts and cables free of corrosion and damage Gabattery posts and cables free of corrosion and damage Gabattery posts and cables free of corrosion and damage Gabattery posts and cables free of corrosion and damage Gabattery posts and cables free of corrosion and damage Gabattery properly sized and secure Gabattery properly alwithin specification Gabattery properly alwithin specification Gabattery properly alwithin specification Gabattery properly alwithin specification Gabat	20	9					60	Batte	ery ł	nas no	o vis	sible	daı	mag	е												
23 Windshield washer fluid sprays properly 24 Wiper blades clear glass properly 25 Wipers return to correct position when off 26 Speedometer functions properly 27 Odometer application registers mileage in every mode 28 Cruise control operates properly 29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 63 Battery properly sized and secure 64 Charging system operating properly sized and secure 65 Engine coolant level within specification 66 Coolant specific gravity to -31° Fahrenheit 67 Change engine oil and filter 68 Check for evidence of oil gel 69 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated Functional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned	21	Front windshield wiper operates properly in all modes																									
Wilper blades clear glass properly Wiper seturn to correct position when off Speedometer functions properly Odometer application registers mileage in every mode Cruise control operates properly A/C operates properly No abnormal noise or vibration/steering wheel shimmy during road test No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody Frame/Unibody condition Panel alignment and fit Lower body and underbody condition Suspension-related items for wear/leaks and proper performance Wiper blades clear glass properly 64 Charging system operating properly and within specification 65 Engine coolant level within specification 66 Coolant specific gravity to -31° Fahrenheit Colant specific gravity to -31° Fahrenheit Colant specific gravity to -31° Fahrenheit Colant specification 66 Coolant specification 67 Change engine oil and filter 68 Check for evidence of oil gel 69 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated Frunctional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned	22	Rear windshield wiper operates properly in all modes															rosi	on a	and	dam	ag	Э		Ц	Ц		
25 Wipers return to correct position when off 26 Speedometer functions properly 27 Odometer application registers mileage in every mode 28 Cruise control operates properly 29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal tire vibration/steering wheel shimmy during road test 34 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 55 Frame/Unibody condition 76 Panel alignment and fit 77 Lower body and underbody condition 78 Suspension-related items for wear/leaks and proper performance 68 Coloant specific gravity to -31° Fahrenheit 69 Change engine oil and filter 60 Colant specific gravity to -31° Fahrenheit 61 Change engine oil and filter 62 Change engine oil and filter 63 Check for evidence of oil gel 64 Check for evidence of oil gel 65 Check for evidence of oil gel 67 Change engine oil and filter 68 Check for evidence of oil gel 69 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned	23	Windshield washer fluid sprays properly																						Ц	Щ		
26 Speedometer functions properly 27 Odometer application registers mileage in every mode 28 Cruise control operates properly 29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 66 Coolant specific gravity to -31° Fahrenheit 67 Change engine oil and filter 68 Check for evidence of oil gel 69 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated Functional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned		, , , ,	Ц	Ц															thin	spe	CITIC	ation		Н	Н		
27 Odometer application registers mileage in every mode 28 Cruise control operates properly 29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 39 Odometer application registers mileage in every mode 30 Change engine oil and filter 68 Check for evidence of oil gel 69 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned		·						_																H	H		
28 Cruise control operates properly 29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal tire vibration/steering wheel shimmy during road test 4 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Under-body 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 68 Check for evidence of oil gel 69 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated Frunctional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned											_	,	,		I F	arırı	enn	eit						\mathbb{H}	H		
29 Heater operates properly 30 A/C operates properly 31 No abnormal noise or vibration from engine 32 No excessive wind or road noise 33 No abnormal tire vibration/steering wheel shimmy during road test 4 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Under-body 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 39 Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated Frunctional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned									0	0														H	H		
and washer fluid at proper levels 70 Under-hood fluids clear and uncontaminated Functional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned			H	H			69							_	n. t	ran:	sfer	cas	se. r	oowe	er st	eerina		Ħ	Н		
No abnormal noise or vibration from engine No excessive wind or road noise No abnormal tire vibration/steering wheel shimmy during road test No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody Frame/Unibody condition Panel alignment and fit Suspension-related items for wear/leaks and proper performance 70 Under-nood fluids clear and uncontaminated Functional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned			H	H															, [
32 No excessive wind or road noise 33 No abnormal tire vibration/steering wheel shimmy during road test 34 No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance Functional & Walkaround 71 Owner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational 73 Battery voltage gauge operational 74 Engine temperature gauge operational 75 Horn operates properly 76 Airbag(s) present with no evidence of deployment 77 Headlights are properly aligned			H	П			70	Und	er-h	ood fl	uids	cle	ar a	nd u	ınc	onta	amir	nate	d								
No abnormal tire vibration/steering wheel shimmy during road test No abnormal squeaks/rattles within the interior of the vehicle Frame, Structure & Underbody Frame/Unibody condition Panel alignment and fit Suspension-related items for wear/leaks and proper performance Towner's Manual and TCUV Warranty Supplement in dealer's possession 72 Fuel gauge operational Rattery voltage gauge operational		and the second of the second o	Ħ	П				Eun	otic	anal	9. V	Vall	kar	01111	d												
A No abnormal squeaks/rattles within the interior of the vehicle							71									ant	v Sı	ınn	lem	ent ir	1						
Frame, Structure & Underbody 35 Frame/Unibody condition 36 Panel alignment and fit 37 Lower body and underbody condition 38 Suspension-related items for wear/leaks and proper performance 39 Frame, Structure & Underbody 40 Figure 1 41 Engine temperature gauge operational 42 Figure 2 43 Frame/Unibody condition 44 Engine temperature gauge operational 45 Horn operates properly 46 Airbag(s) present with no evidence of deployment 47 Headlights are properly aligned		, ,					' '						, 50		. ui i	JI IL	, 0	~PP	J111	O1 11 11					ш		
35 Frame/Unibody condition									-																		_
36 Panel alignment and fit		to the state of th							-	_	_	_															
37 Lower body and underbody condition			님	片				_				_	_	e op	oera	atior	nal							\vdash	Щ		Ш
38 Suspension-related items for wear/leaks and proper performance		9	\exists	님																				\vdash	닏		
			\exists	님					. ,							je c	or ae	plo	yrne	HI				\vdash	⊢		
		· · · · · · · · · · · · · · · · · · ·	H	H					_				,	_		ner	·lv							\dashv	님		

WHITE COPY: DEALERSHIP

YELLOW COPY: CUSTOMER

HARD COPY: SERVICE (USED-CAR DEPARTMENT)

1				
		Meets	Adjust/	
	Functional & Walkaround (cont.)	Stds		N/A
79	Tail lights operate properly			
80	Brake lights operate properly			
81	Side marker lights operate properly	H	H	
1		=	H	
82	3 1- 3			
83	License plate lights operate properly			
84	No cracked or broken lenses of exterior lights			
85	Instrument panel/warning lights operate properly			
86	HVAC panel/lights operate properly	Ħ	Ħ	
		H	H	
87	Instrument panel light dimmer operates properly			
88	Turn signals operate properly and self-cancel			
89	Hazard flashers operate properly			
90	Rear-view interior mirror operates properly	\Box	$\overline{\Box}$	
91	Exterior mirrors' operation and condition	H	H	
1	•	H	H	
92			\sqcup	
93	Glass free of cracks, stars and large chips			
94	Window tinting clear and conforms to local requirements			
95	Dome/courtesy lights operate with door cycles			
	Windows operate properly	Ħ	H	
		\dashv	\vdash	
97			\Box	Щ
98	Power windows operate from master switch and all door switches			
99	Audio/Cassette/CD/Aux system working properly; CD cartridge			
-	present (if equipped)	ш	ш	ш
100	Audio speakers do not rattle at high volume and function properly			
	Antenna is present and functional	Ħ	Ħ	Ħ
	•	\vdash	님	\vdash
	Clock operates properly	닏	닏	\vdash
103	12v ACC power outlet operates properly			
104	Ashtrays (if equipped) are present and operate properly			
105	Headliner, sun visors, dash pad, upholstery, console,			
	cup holders, trim panels and carpet are in place, in good		ш	
	condition and operate properly			
106	Driver floor mat (if equipped) is appropriate floor mat for the vehicle,			
100	properly secured and not stacked on top of another floor mat			
107				
107		Ш		
108	Door locks, including child safety locks, operate properly			
109	Remote keyless entry system and smart key system operate properly			
1	Master key is present	$\overline{\Box}$	$\overline{\Box}$	
111		H	H	
1		\vdash	\vdash	\perp
	Seat adjustments and seat heater(s) operate properly		Ш	
113	Memory seat control operates properly			
114	Headrests function properly			
	Defogger indicator light operates properly			
		Ħ	H	$\overline{\Box}$
116	Rear defogger operates properly			
	Rear defogger operates properly			
116	Rear defogger operates properly Luggage compartment light operation and trim appearance			
116 117 118	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains			
116 117 118 119	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly			
116 117 118 119 120	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly			
116 117 118 119 120 121	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly			
116 117 118 119 120 121	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly			
116 117 118 119 120 121 122	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly			
116 117 118 119 120 121 122 123	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition			
116 117 118 119 120 121 122 123 124	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present			
116 117 118 119 120 121 122 123 124	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32"			
116 117 118 119 120 121 122 123 124 125	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining			
116 117 118 119 120 121 122 123 124 125	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire			
116 117 118 119 120 121 122 123 124 125 126 127	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean			
116 117 118 119 120 121 122 123 124 125 126 127	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire			
116 117 118 119 120 121 122 123 124 125 126 127 128	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened			
116 117 118 119 120 121 122 123 124 125 126 127 128 129	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked	atio	10000000000000000000000000000000000000	
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certific			s)
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certifice Detailing Standards and Process Notes For Additional comparison of the process of			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certific			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certifice Detailing Standards and Process Notes For Additional comparison of the process of			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certificate Exterior Appearance Body surface condition			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certific tee Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certifice Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certifice e Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of removable scratches			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certifice Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certifice tee Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of wax residue			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certificate Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of wax residue Wheels/wheel covers are clean			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire resent Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certificate Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of wax residue Wheels/wheel covers are clean Wheel wells are clean			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certificate Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of wax residue Wheels/wheel covers are clean			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire resent Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certificate Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of wax residue Wheels/wheel covers are clean Wheel wells are clean			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 (S	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire resent Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certificate Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of wax residue Wheels/wheel covers are clean Wheel wells are clean			
116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138	Rear defogger operates properly Luggage compartment light operation and trim appearance Luggage compartment is clean, free of debris, no stains Hood and luggage compartment latches operate properly Interior remote luggage compartment release operates properly Emergency trunk release operates properly Emergency trunk release operates properly Fuel door release operates properly Spare tire's cover appearance and condition Spare tire present Spare tire has correct air pressure and a minimum of 5/32" tread remaining No signs of damage to spare tire Spare tire and storage areas are clean Spare tire is securely fastened Jack and tools are correct, present and secured Acceptable aftermarket items checked Removal of unacceptable aftermarket items Detailing and Appearance Repair Certificate Detailing Standards and Process Notes For Addition Exterior Appearance Body surface condition Exterior is washed, clean and free of water spots Paint is free of swirl marks and has an even, high luster Paint is free of wax residue Wheels/wheel covers are clean Wheel wells are clean Tires are clean and properly dressed			

142 Engine and compartment are properly dressed

Inspection Check Sheet number:

	Interior Appearance		Adjust/	h:/-
43	Interior Appearance Interior is free of debris	Stds	Repair	N/A
	Dash and vents are clean and properly dressed			
	All crevices are clean Ashtrays and lighter are clean (if equipped)			
	Door jambs are clean	Н		
	Glove box and console compartments are clean			
	Cabin air filter condition			
	Seats, carpets, floor mats (if equipped) and headliner are free of stains	\vdash		
51 52	Free of odor, including heavy fragrance Glass is clean and free of streaks	H		
	Exterior Repairs			
	Body is free of all dents			
	Body is reasonably free of dings	Н		
	Paint is reasonably free of scratches and chips Vehicle is free of improper paint repairs or mismatched color	H		
57		П	П	
58	Bumpers are free of cuts, gouges and mismatched paint			
	Interior Repairs	_		
59	Interior leather, vinyl, plastic, carpet and fabric surfaces are free of holes, rips, tears, excessive wear or fading			
60	No evidence of previous improper interior repairs			
	Additional Inspection Items (Where Applie	cable)	
1	"Fade-away" dome light operates properly			
2	Sunroof/convertible top operates properly through full range of positions			
	Convertible top lockout function operates properly			
	Radio security codes cleared	H	H	\exists
6	Navigation system operates properly and memory system cleared Transfer case smoothly switches from 2WD to 4WD and back			
	from 4WD to 2WD			
7	Truck bed liner is in good condition and secured			Н
8	Truck bed-liner is in good condition and secured Tailgate operates properly			H
	Backup camera operates properly			
11	Bluetooth® searches for signal			
12	SOS (Safety Connect) light illuminates green			
	Lane Keep Assist operates properly	Н		H
14 15	Dynamic Radar Cruise Control/Pre-Collision Systems operate properly Intelligent Parking Assist operates properly	H		H
	Hybrid Components			
1	Hybrid battery			
	Battery control module (battery voltage sensor)	П	П	П
3	Hybrid power management control module			
	Electric motor/generator operates properly	Ц	Ц	Ц
	ECVT operates smoothly and properly	H	Н	Н
	Power inverter operates properly Inverter coolant level			H
	EV/Eco/Power modes operate properly	П	П	П
9	Check transaxle "park" mechanism			
	Multi-information display operates properly			
11	Touch Tracer display operates properly Hill Start Assist Control operates properly	H	H	\exists
	Remote air conditioning system (if equipped) operates properly	H	H	\exists
14	Solar-powered ventilation system (if equipped) operates properly			
	Required Technician Signature			
	I certify that all mechanical items have been inspected.			
	Toyota Trained Technician Date			
	Required Manager Signature			
	I certify that all mechanical repair standards have been m	et.		
	Service Manager Date			
	I certify that all detailing and appearance standards have bee	n met.		
	Used Car Manager Date			
	Customer Signature I acknowledge that I have received a copy of the 160-Point Inspection the Vehicle History Report and the Used Vehicle Warranty Supplem	Check ent Ma	s Sheet, anual.	
	Customer Date			
	Date			



Bobby Rahal Toyota

6711 Carlisle Pike Mechanicsburg, PA 17050 Phone (800) 778-0850 www.bobbyrahal.com

CLIENT NO. 63300	ADVISOR Dave Reider	1405 TAG NO.	08/10/17	INVOICE NO. TOIS127056
BOBBY RAHAL TOYOTA	LABOR RATE LICENSE NO. DSX9234	MILEAGE 6018	COLOR RUBY FLARE/	STOCK NO. T58725A
6711 CARLISLE PIKE	YEAR/MAKE/MODEL 17/TOYOTA/CAMRY/LE A	UTOMATIC	DELIVERY DATE 07/15/06	DELIVERY MILES 6018
4			SELLING DEALER NO. 37149	PRODUCTION DATE
MECHANICSBURG, PA 17050	F.T.E. NO. 21528781	P.O. NO.	R.O. DATE 08/09/17	
RESIDENCE PHONE BUSINESS PHONE 717-691-0500	COMMENTS	E# 2ARN246911		MO: 6023
J# 2 45TOZZDELUXE DELUXE HOURS CUSTOMER REQUEST DELUXE DETAIL - S AND HAND WAX, SHAMPOO AND VACUUM I CLEAN AND DRESS WHEELS AND TIRES COMPLETED DELUXE DETAIL AS REQUEST G.O.G. & SUPPLIES	SPECTION K. PPTIONUNIT WIPER BLA WIPER BLA JOB # 1 TOTAL LABOR & TECH(S):1924 TEAM CLEAN ENGINE, WASH NTERIOR, CLEAN WINDOWS AND TED BY CUSTOMER. JOB # 2 TOTAL LABOR & 25.000 /UNIT TOTAL -	153.00 PRICE- 8.32 5.42 5.42 13.74 PARTS 166.74 112.00 PARTS 112.00 25.00 25.00	for ch Bobby for servi vehicle. O staff wo to make are 100%	k You oosing Rahal cing your Our entire rks hard sure you satisfied. ou Again!
ROTORS FRONT 27.63/27.66 AND REAR 9.95/9.98 TOTALS	TOTAL LAB TOTAL PAR TOTAL SUB TOTAL G.O TOTAL MIS TOTAL TAX TOTAL TAX	TTS 13.74 LLET 0.00 0.G 25.00 CC.CHG. 0.00 CC.DISC 0.00 0.00	www.bobb for you	sit yrahal.com ur next vice atment!
PAGE 1 OF 1	[END OF INVOIC	E] 12:38pm		